



TECHNICAL SERVICE BULLETIN

POLY GAS CADDIES (25GC-P, 25GC-PI, 25GC-P2)

It has been brought to our attention that the following 25-gallon JohnDow "Poly" Gas Caddies manufactured between June 15th and July 15th 2008 may form a stress crack in the body of the tank. These cracks have the potential to form a slow leak. The models affected are:

JDI-25GC-P
JDI-25GC-P1
JDI-25GC-P2

The affected models can be identified by the "Trace Code" which is found on the bottom of each tank. The units affected would have a trace code shown between 175-8-1 and 185-8-3.

If you have a unit with this trace code, immediately discontinue use and transfer the contents into another container. Immediately contact JohnDow Industries for free replacement.

To request a replacement or for additional information contact JohnDow Industries at (800) 433-0708 8:00am – 5:00pm EST, Monday through Friday.

JohnDow Industries has received no reports of injury or property damage associated with this issue.

Please share this TSB with any of your customers that may have purchased these models and could be affected by this potential failure.